

BRUNSG ASSOCIATES, INC.
P.O. BOX 588
Windsor, CA. 95492
Telephone: (707) 838-3027
Fax: (707) 838-4420

BORING NO.: **B-4**

SHEET 1 OF 1

PROJECT: **COTATI STATION**

LOCATION: **Cotati, California**

PROJECT NO.: **771**

LOGGED BY: **SMS**

COORDINATES:

SURFACE ELEVATION:

DATUM:

SAMPLE INFORMATION						STRATA	WELL CONSTRUCTION DETAIL
DEPTH FEET	LAB SAMPLE	SAMPLE TYPE	BLOW COUNTS	Recovery (%)	PID (ppm)		
5			8 14 17		5.0		
10			21 19 21		5.0		
15			9 14 23		5.0		
20			7 9 18		5.0		
25			12 18 25		5.0		
DARK BROWN CLAY (CL) dry to moist, stiff, ~5% fine to very fine-grained sand, ~10% silt, ~85% clay							
BROWN CLAY (CL) dry to moist, very stiff, ~10% fine to very fine-grained sand, ~15% silt, ~75% clay							
BROWN CLAY (CL) dry to moist, stiff to very stiff, ~15% silt, ~85% clay							
BROWN SILTY CLAY (CL) wet, medium stiff, trace gravel, trace very coarse-grained sand, ~20% silt, ~80% clay, subangular gravel up to 8mm							
BROWN SILTY CLAY (CL) moist to wet, ~10% medium to very fine-grained sand, ~30% silt, ~60% clay, trace coarse sand							

DRILLING CONTRACTOR: Clear heart

DRILLING METHOD: 6-inch hollow stem auger

DRILLING EQUIPMENT: Deeprook Dr10K

DRILLING STARTED: 11/22/04 ENDED: 11/22/04

REMARKS Boring drilled to 25.0' BGS.
Sampler driven to 26.5' BGS

See key sheet for symbols and abbreviations used above.



BRUNSG ASSOCIATES, INC.

Job No.: 771

Appr:

Date: 2/16/05

LOG OF BORING B-4

COTATI STATION
8348 Santero Way
Cotati, California

PLATE

7